Tip Typical installation of an MD44FT field installable jack

Mini DIN 4 - S-Video Jack

Black Center Black Shield

Yellow Center Yellow Shield

STEP 1

Prepare coaxial lines.



Insert center conductors, shields and tighten set screws.



Secure cable with cable tie to connector.



Attach to faceplate and install.